Qty:

User:

Tuesday, 6/13/2006 3:29:02 PM

Linda Lacelle

#### **Process Sheet**

Customer Job Number

: CU-DAR001 Dart Helicopters Services

: 27523

**Estimate Number** P.O. Number

: 10645

This Issue

Prsht Rev.

First Issue

:NIA

: 6/13/2006

: NC

: 6/12/2006 : 25484

S.O. No. : NIK

: PURCHASED PARTS

**Part Number** 

**Drawing Name** 

**Drawing Number** 

: D2429041 D2429 REV C1

**Project Number Drawing Revision** 

: N/A : C1

**Material Due Date**  AIM:

: 6/30/2006

: SPRING CLIP ASSEMBLY

Each

Written By Comment

**Previous Run** 

Checked & Approved By

: Est. D 02.03.06

Added note at step 7 NG

OMMENTBELO

Additional Product

Job Number:



Seq. #:

1.0

**Machine Or Operation:** 

Description:

**Comment: FLOW WATER JET** 

WATER JET

M304S20GA 2.0

304/316 .040 Sheet

FLOW WATER JET

Comment: Qty.:

0.0500 sf(s)/Unit

Total:

304/316 .040 Sheet

0.2500 sf(s)

SB

SAO

3.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING-RESOURCE #1

Recieive & Inspect for Transit Damage

Ensure Material Release Note is attached

INSPECT WORK TO CURRENT STEP



Comment: INSPECT-WORK TO CURRENT STEP SMALL FAB 1 5.0

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1 SAO 06:08.04



2-Bend D2429-1 as per Dwg D2429

6.0

MS20470AD45

1-Deburr



Rivet, Universal Head



Comment: Qty.:

1.0000 Each(s)/Unit Total:

5.0000 Each(s)

Rivet, Universal Head

Pick:

Qty Part number Description Batch



Date: Tuesday, 6/13/2006 3:29:02 PM Úser: Linda Lacelle **Process Sheet** Drawing Name: SPRING CLIP ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Job Number: 27523 Part Number: D2429041 Job Number: Seq. #: **Description: Machine Or Operation:** MS20470AD4-5 Rivet 1 7.0 AN960JD6L Washer Comment: Qty.: 2.0000 Each(s)/Unit Total: 10.0000 Each(s) Washer Pick: Description Batch Qty Part number MS519 2 AN960JD6L Washer SAD 06:07/20 NOTE: 2 D2429-1 required for 1 assy. SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 8.0 Comment: Assemble D2429-041 as per Dwg D2429 SAD 06:07! 9.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 10.0 PACKAGING 1 PACKAGING RESOURCE #1 **Comment: PACKAGING RESOURCE #1** Identify and Stock Location: 5741 DOCUMENT CONTROL 11.0 Comment: DOCUMENT CONTROL Inspection Level 21

Job Completion

\$ 06.07.24

Dart Aerospace Ltd. Monday, 6/12/2006 3:43:20 PM User: Kim Johnston **Process Sheet** : SPRING CLIP ASSEMBLY Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** Job Number : 27523 **Estimate Number** : 10645 P.O. Number **Part Number** : D2429041 S.O. No. : : D2429 REV C1 This Issue : 6/12/2006 **Drawing Number** : N/A Prsht Rev. : NC Project Number : // : PURCHASED PARTS : C1 First Issue Type **Drawing Revision** : 25484 Material **Previous Run Due Date** : 6/30/2006 Qty: 5 Um: Written By Checked & Approved By Added note at step 7 Comment : Est. D 02.03 **Additional Product** Job Number: **Machine Or Operation:** Description: Seq. #: PG **PURCHASING** 1.0 1264 Note: Qty 2 pleces required per assembly Make 02429-1 Alat Pattern as per Dwg D2429 Material release note required 2.0 Comment: Oty.: -1:0000 Each(s)/Unit 06:06:20 Spring Clip Ass'y 3.0 PACKAGING RESOURCE #1 Comment: PAGKAGING RESOURCE #1 Recieive & Inspect for Transit Damage Ensure-Material-Release-Note-is-attached 4.0 INSPECT WORK TO CURRENT STEP

SMALL & MEDIUM FAB RESOURCE 1

Comment: INSPECT

5.0

SMALL FAB 1

1-Deburr

Comment: SMALL & MEDIUM FAB RESOURCE 1

2-Bend D2429-1 as per Dwg D2429

WORK TO CURRENT STEP

Each

## Dart Aerospace Ltd

W/O:		WORK ORDER CHAI	NGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
06-07·20	0	Add Note for 2 pieces regid for lassy.		-			
		Parm. Chunge.	-				ds-57-30

NCR:			WORK ORDI	ER NON-CONFORMAN	CE (NCR)	ICR)					
		Description of NC		Corrective Action Section B		V:6:4:		Approval QC Inspector			
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Verification Section C	Approval Design Mgr				
						:					
		,									

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA: N	1/C C	losed:	Date:

Monday, 6/12/2006 3:43:20 PM Date: User: Kim Johnston **Process Sheet Drawing Name: SPRING CLIP ASSEMBLY** Customer: CU-DAR001 Dart Helicopters Services Job Number: 27523 Part Number: D2429041 Job Number: Description: Seq. #: **Machine Or Operation:** MS20470AD45 6.0 Rivet, Universal Head Comment: Qty.: 5.0000 Each(s) 1.0000 Each(s)/Unit Total: Rivet, Universal Head Pick: Description Batch Qty Part number MS20470AD4-5 Rivet 1 7.0 AN960JD6L Washer Comment: Qty.: 2.0000 Each(s)/Unit Total: 10.0000 Each(s) Washer Pick: Qtv Part number Description Batch AN960JD6L Washer NOTE: 2 D2429-1 required for 1 assy. SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 8.0 Comment: Assemble D2429-041 as per Dwg D2429 9.0 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: DOCUMENT CONTROL 11.0 Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion

### **Dart Aerospace Ltd**

W/O:		WORK ORDER CHA	NGES					
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
			;					
			·					
		WORK ORDER NON CONFOR		. /\.				

NCR:		W	ORK OR	DER NON-CONFORMANCE (N	VCR)			
	_	Description of NC		Corrective Action Section B		/erification	Approval	Approval
DATE	STEP	Section A	Initial Design Mgr		ign & Date	Section C	Approval Design Mgr	Approval QC Inspector
,			. **					
							,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	 Date:
NOTE: Date & initial all entries	· ·			QA: N	I/C C	losed:	 Date:






DESIGN KE	DRAWN BY	DART AEROS HAWKESBURY, ON	
CHECKED_	APPROVED	DRAWING NO.	REV. C
A	#	D2429	SHEET 1 OF 1
DATE		TITLE	SCALE
00.06.26		SPRING CLIP	1:1
Δ	95.07.21	NEW ISSUE	

# BELEASE)

00.0	6.26	SPRING CLIP 1:
Α	95.07.21	NEW ISSUE
В	97.10.09	ADDED ASSEMBLY
C.	00.06.26	1.969 WAS 2.100; 0190 WAS 0.321
CI	(P of 01.03.27	Ø 0.138 WAS Ø 0.128



D2429-1 SPRING CLIP (2)

MS20470AD4-5 RIVET (1)
AN960JD6L WASHER (2)

D2429-041 SPRING CLIP ASSEMBLY

SHOP COPY

RETURN TO

ENGINEERING

UNCONTROLLED COPY

SUBJECT TO AMENDMENT

WITHOUT NOTICE

MATERIAL: AISI 304/316 SS 0.040 THICK 0.50 WIDE WORK ON TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED ALL DIMENSION ARE IN INCHES

Copyright © 1995 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART AEROSPACE LTD	Work Order: 27523
Description:	Part Number: D2429-1
Inspection Dwg: , Rev:	Page 1 of 1

#### FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing	Tolerance	Actual	Accept	Reject	Method of	Comments
Dimension		Dimension	•	9	Inspection	
1.183	±0,010	爾1.178			Vern	
1,779	±0,010	1.775			Vern	
0.250	±0.010	0.246			Vern	
0,500	20,010	0.495			Vern	
1.969	+0.005/-0.001	1.966			Vern	
\$0.138	1	80,141	)		Vern	
80,128	40,005/-0,001	80.29	\ \		Vern	
				`		
				-		
	·					
					,	

Measured by:	SAD	Audited by:	MS	Prototype Approval:	
Date:	06:06:20	Date:	06/06/20	Date:	

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	